

Subject: Elevator hinges play check and its elimination.

Affected: WT9 DYNAMIC
S/No.: from DY 004/01 to DY 019/02

Compliance: Immediately

Mass data: Weight change – none
Moment change – none

Reason: From the operation above mentioned aircrafts has been discovered, that in the elevator hinges comes a play after some time of operation.

Arrangements: Carry out an elevator hinge play check.



If the play has been discovered it is necessary to glue the brass bushings into the elevator hinges on stabilizer. Follow the instruction No. 3120 ZBWT9 02A/2006.

If the excessive play was not discovered glue the bushings at the nearest annual inspection or 100 hrs, inspection, whatever comes first.

Procedures: Instruction No. 3120 ZBWT9 02A/2006, in Appendix.

Material information: The material necessary to carry out this bulletin is mentioned in Instruction 3120 ZBWT9 02A/2006, in Appendix.

Parts sent by manufacturer:

- Bush of stabilizer hinge P/N: DYN-601-34 4 pieces
- carbon fiber unidirectional CF 140 = (170 x 1000 mm)
- glass fiber twill weave 92 110 + (170 x 1000 mm)
- cotton flocks, - resin L-285, - hardener L 287

Material – will be supplied on request by AEROSPOOL, or Authorized Distributors or their Service Center.

Documentation: Results of this check and work, note into documentation of the aircraft with date and signature of service man which execute the procedure. Inform the airplane producer and authorized distributor about which procedure had been performed and the airplane serial number.

Prievidza 26th October 2006

AEROSPOOL spol. s r.o.
Approval SK.21G.0002
92/03 PRIEVIDZA
SLOVAK REPUBLIC

Issued:.....

Approved CAA of Slovak republic at:

N : 344 - 233 /2007 05th February 2007

Approved by: CAA of Slovak republic