

Subject: Change of the air filter.

Affected: UL-Aircraft WT9 DYNAMIC
S/No.: All up to DY – 057/2004

Compliance: Till the nearest inspection.


Mass data: Change of the weight – none
Change of the moment – none

Reason: In the common operation of the UL – Aircraft WT 9 DYNAMIC has occurred short irregularities of the engine run. After regular carburetor check was there discovered a little dirt (flies and a little pieces of the grass) because the leakage and deformations of the air filter seat.

Arrangements: Carry out the air filter check.

If you will discover the leakage or deformation on the air filter seat the type Purolator Typ A1794 is recommended to change the filter for the filter type Kingdragon AL 13 or filter type SF sprint filter P 102 Panel (D1 167 D2 89).

Procedures: Change the filter following the instruction:



Safety pin

Airbox lock

Airbox preheating rod

1. Demount the upper engine cowling
2. Remove the Airbox lock safety pin
3. Disconnect the Airbox preheating rod
4. Release the Airbox lock
5. Unclamp the part with filter
6. Replace the old air filter for the new one
7. Close and lock the Airbox, check the bottom lock connection
8. Secure the lock with safety pin
9. Reconnect the Airbox preheating rod
10. Mount the upper cowling back

Material information:

Material – will be supplied on request by AEROSPOOL, or Authorized Distributors or their Service Center.

References: Results of this check and work note into documentation of the aircraft with date and signature of service man which execute the procedure and inform the airplane producer or authorized distributor about the serial number on which has been this recommendation carried out.

Prievidza 22nd September 2004

Issued:.....

Approved at:

Approved by: