

**Subject:** Locking of the wing's main pin by the Fokker pin.


**Affected:** Aeroplane WT-9 Dynamic (all serial numbers).

**Compliance:** Before next flight.

**Mass data:** Weight change- none  
Moment change- none

**Reason:** From the aircraft operation rose suspicion of the Fokker pin release which safeguards wing's main pin situated in the cockpit.

**Arrangement:** 1. Verify correct locking of all Fokker pins used in the plane.  
2. We recommend to replace the Fokker pins with functional length 35mm and 51mm with Fokker pins with functional length 20mm which safeguards wing's main pin situated in the cockpit.



Fokker pins  
20 mm 35 mm 51 mm



51 mm



35 mm




20 mm

**Material:** Two pieces of Fokker pin Lw = 20 mm. It is possible to order it in the TOST Company or at your Dynamic sales agent.

**Fokkernadeln** Material: Federstahl alle Maße in mm

Breite b	lichte Weite Lw	Drahtstärke d	Artikel-Nr.	Preis
5	20	1.4	920010	0,52
12	35	1.2	920011	0,86
8	51	1.3	920012	0,84



Tost GmbH Flugzeuggerätebau München  
Thalkirchner Straße 62 80337 München ☎ 089 - 544 599 - 0  
Fax 089 - 544 599 - 70 e-mail: info@tost.de LBA-Nr. G.0065

**Documentation:** Results of this check and work, note into documentation of the aircraft with date and signature of service man which execute the procedure. Inform the airplane producer and authorized distributor about which procedure had been performed and the airplane serial number.

Prievidza 3<sup>th</sup> September 2008

**AEROSPOOL spol. s r.o.**  
Approval L-2-012/SK 2007  
871 03 PRIEVIDZA  
SLOVAK REPUBLIK

Issued: .....

Approved at:

- 3. 09. 2008

Approved by: