AEROSPOOL SPOL. S R.O.	**Manufacturer Recommendation** No. DV WT9 07B/2007	Sheet: 01 Number of sheets: 01

Subject: Metal parts corrosion: Front leg of fixed landing gear,
Flaps torsion tube,
Elevator actuating bracket.

Affected: WT9 DYNAMIC .
S/No.: All serial numbers up to DY – 184/2007

Compliance: At the next inspection

Mass data: Weight change – none
Moment change – none

Reason: On the specified metal parts has been discovered some marks of corrosion due aggressive conditions as a see coast place or places with big temperature changes.

Arrangements: Apply into the hollow parts the suitable anticorrosion prevention coating.

The most affected parts: Front leg of fixed landing gear, Flaps torsion tube and Elevator actuating bracket.

Material information:

Description	**Content**	**Article number**	**EAN-code**
"Bitumen Based Undercoating"	1.000 ml	000033	8711347000333"

Material – will be supplied on request by AEROSPOOL, or Authorized Distributors or their Service Centre or you can buy it yourselves on www.motip.nl

Documentation: Results of this check and work, note into documentation of the aircraft with date and signature of service man which execute the procedure. Inform the airplane producer and authorized distributor about which procedure had been performed and the airplane serial number.

Prievidza 5th December 2007 AEROSPOOL spol. s r.o. Approval SK.21G.0002 971 03 PRIEVIDZA SLOVAK REPUBLIK Issued:.....	Approved at: 11. 12. 2007 Approved by: